

ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS

L P C F C O 5 5 C
(1) (8) (9)

OBSERVATION REPORT - SITE INVENTORY NO. 16312109

(11) (18)

St. Clair

CO. - L.P.C.

Region # 5

Date 07/21/83
(20) (25)

Sauget

(Location)

(Responsible Party)

Samples Taken: Yes () No (X)

Time: From 11:00 a.m.

Ground Water () Surface () Other ()

To 11:50 a.m.

Photos Taken: Yes () No (X)

Interviewed Jack McCoy

Letter Sent (Yes or No) No

Weather Sunny, dry, ~98°

Inspector D M S

Previous Inspection 5-25-83

Previous Correspondence 9-14-80

Site Open: Yes (X) No ()

OPERATIONAL STATUS:

TYPE OF OPERATION:

AUTHORIZATION:

Operating (X)

Landfill ()

Storage (X)

E.P.A. Permit (X)

Temporarily Closed ()

Random Dump ()

Salvage ()

Variance ()

Closed Not Covered ()

Other Incinerator (X)

A.C.D. ()

21(e) ()

Closed and Covered ()

Quantity Received Daily(1-6) 2

(30)

Board Order ()

Illegal (5) ()

(31)

IMPROVED

LPC 4 1/79 5,000

SAME

DETERIORATED

I (S) or D S
(62)

GENERAL REMARKS: Due to the recent changes occurring at the site, an update was needed to bring the field staff up to date. Jack McCoy, partial site owner, accompanied me on the inspection. Channel 4 News was also at the facility due to waste being placed in storage from the Missouri Calahan site (hazardous drums site). Per Mr. McCoy, 600 drums were to be placed into storage and later disposed at TBI. An 800 drums were already in storage in the recently erected 3rd storage building. Drum storage areas remain with drums being stacked.

INTERVIEW: 3 high. Tank #20 was being pressure tested while I was at the site. All valves and tanks are color coded to prevent or reduce the potential for mistakes. Approximately 10 refrigeration trucks are located within the fenced site area, containing hospital wastes. Mr. McCoy stated that he hopes to have the incinerator operational by the first week in August. Permits from APC have not yet been issued.

DIAGRAM:

